

## **Packaging**

### **Twinthread Woodscrews**

In 2 part cardboard boxes without wasted space inside. Plain gloss box in white or blue\*. Box to be sealed with tape. Labeled with size, description and quantity on the smallest side bar-code to be on label on bottom of box. (Box should be strong enough not to split when dropped from 1.5Metres.)

\* Square Lock screws are to be packed in a blue & white check box.

Outer cardboard cartons not to exceed 20KG in weight. (Boxes must be packed tight inside to ensure no movement during shipping) Labeled with size, description and quantity

Palletized on strong wooden pallets which can be lifted by a hydraulic hand truck as well as a fork lift. with wooden side re-enforcement.

**Drywall Screws** – as above but packed in 1000

### **Machine Screws M3.5 & M4**

In plastic bags of 100 no less than 600 GAUGE (150 mic). Bag needs to be heat sealed. Labeled with size, description and quantity. (Bag should be strong enough not to split when dropped from 1.5Metres.) 10 x 100 bags to be placed in an outer bag .

Outer cardboard carton not to exceed 20KG in weight. (Bags must be packed tight inside to ensure no movement during shipping) Labeled with size, description and quantity

Palletized on strong wooden pallets which can be lifted by a hydraulic hand truck as well as a fork lift.

### **Brass Setscrews, Nuts & Washers**

In plastic bags of 100 no less than 600 GAUGE (150 mic). Bag needs to be heat sealed. Labeled with size, description and quantity. (Bag should be strong enough not to split when dropped from 1.5Metres.) 10 x 100 bags to be placed in an outer bag .

Outer cardboard carton not to exceed 20KG in weight. (Bags must be packed tight inside to ensure no movement during shipping) Labeled with size, description and quantity

Palletized on strong wooden pallets which can be lifted by a hydraulic hand truck as well as a fork lift.